01807.001545. <u>PATENT</u>

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Examiner: J.M. Perilla

roup Art Unit: 2634

Certificate

OCT 1 2 2005

of Correction

In re Patent of:

PHILIPPE LE BARS ET AL.

Appln. No.: 09/805,176

Filed: March 14, 2001

For: METHOD AND DEVICE FOR

**EVALUATING THE NOISE** 

ASSOCIATED WITH TURBOCODES,

AND SYSTEMS USING THEM

U.S. Patent No.: US 6,898,251 B2

Issued: May 24, 2005 : October 5, 2005

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

# CERTIFICATE OF CORRECTION \_\_\_\_UNDER RULE 322

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form, in duplicate, is enclosed.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Leonard P. Diana Attorney for Patentees Registration No. 29,296

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY\_Main 518234v1

)

# Stable Ould Here STRINE

UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

US 6,898,251 B2

**DATED** 

May 24, 2005

INVENTOR(S) :

PHILIPPE LE BARS ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 10:

Line 17, " $\hat{x}$ ,  $\hat{y}1$ ,  $\hat{y}2$ ," should read --x, y1, y2,--; and Line 51, "the" should read --a--.

#### **MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,898,251 B2</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

NY Main 518234v1